



Only numbered Service Parts are available.



Only numbered Service Parts are available.



Only numbered Service Parts are available.

This is a detailed exploded view diagram of a mechanical assembly, likely a piece of industrial equipment. The diagram shows the main housing and various internal components, including a motor, gears, belts, and structural frames. Numerous parts are labeled with blue numbers, indicating they are serviceable components. The parts are arranged in an exploded manner to show their relative positions and how they fit together. The background is white, and the parts are drawn in a clean, technical style. A large, faint watermark is visible across the center of the diagram.

Numbered parts shown in the diagram include:

- 501, 505, 506, 507, 508
- 510, 511, 513, 514, 515, 517, 518, 519, 521, 525, 526, 527, 528, 529
- 700, 701, 703, 705